



1/10




FIG. 1








FIG. 2B



50



DETAIL B-1



B-1

52 54

50




FIG. 2C




FIG. 3A




FIG. 3B




FIG. 3C




FIG. 4



FIG. 5A





FIG. 5B

STEP CHANGE IN FLOW: 0-80 SLPM  
 AMBIENT TEMPERATURE: 20 DEGREES C  
 HEATING RESISTOR: 100% PWM



not receive the follow  
 ing 100% PWM